			-						
Scrap Scrap							ח נ		
Scrap Scrap						FAIR	ν 4 π		
Scrap Scrap	Inspector	Rev Letter	Yes / No Check	Time Of Day	Submitted		3 Z L		
Scrap	Inspection Record	First Part	-		\mathbb{H}			Special Notes / Instructions	Specia
Scrap									ROUTING:
Scrap									
Scrap	7								
Scrap									
Scrap			+						
Scrap									
Scrap									
Scrap									
Scrap									
Scrap									
Scrap			-						
Scrap									
Scrap						ō		88	12/14
	Notes		Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
put/8hrs		1 2077 111		Time	Hrs.				
Thru-		Pcs./Hr		Cycle	Setup	S		Mach. No.	
						Do not require traceability.	Do not requi	Caps/Plugs	Caps
				-	by "Lot Number	Located on the bag followed by "Lot Number."	Located on t	Snap Rings	Snap
				box label.	and date on the	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
				etter "M."	arting with the l	Located on the spool label, starting with the letter "M."	Located on t	Copper Tubing	Coppe
				vord "heat."	ectly above the v	Located on the box label, directly above the word "heat."	Located on t	SS	Brazir
				ox quantity.	ox label under bo	Six digit no. located on the box label under box quantity.	Six digit no. I	Flare Nuts	Flan
20151504	G-RING				Numbers	Distinguishing Traceablity Numbers	Distingui		
393842	702-8-3/16	7				10	1	Order Qty	Ord
No(s)	Component(s)	9	LC.	devices, LLC	H	393902	393	Order No.	Ord
Heat Lot/Traceability						702-8-3/16-R	702-8-	Part No.	Par