									 Iraining Meeting 			
	Notes	Inspector	Rev Letter	Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted	се	 Maintenance Tooling 			
Mile of		t Inspection Record	First Part I	5000				e Codes	Down Time	tions	Special Notes / Instructions	Specia
												ROUTING:
	A											
	5											
	(
	Sign	1										
							1					
			*									
									ŋ		gs	2/10
ap Scrap Code	Scrap	Notes			Down Time Code	Down Time	Cum. Total	ე.	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs					Time		Hrs.				
	Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
								lity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
							Located on the bag followed by "Lot Number."	wed by "	the bag follo	ocated on		Snap
						box label.	Use their work order number and date on the box label.	mber and	ork order nu	Jse their w	Flare Tubes	Flare
						etter "M."	Located on the spool label, starting with the letter "M."	oel, starti	the spool lal	ocated on	Copper Tubing	Coppe
			5			ord "heat."	Located on the box label, directly above the word "heat."	l, directly	the box labe	ocated on	Brazing Rings	Brazir
	N/A	A-KF003	,			x quantity.	Six digit no. located on the box label under box quantity.	the box la	located on t	ŝix digit no.	Flare Nuts	Flan
	NIA	DCN516-HT	DC				mbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
	399392	2803-16-3/16-0	280	ľs S					5		Order Qty	Ord
	No(s)	component(s)	Con		LLC	devices, LLC	THE STATE OF THE S		400015	40	Order No.	Ord
	Heat Lot/Traceability	30000±(c)	2			o tro			2803-16-3/16	2803-	Part No.	Par