1										
			7				Training Meeting	6 Vi		
	(R.		5	427	6,2	2-11-16	Setup FAIR	4 3		
	Notes	10,0	Mtrl Check Rev Lett	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2 1		
新型子的数型的		First Part Inspection Record	First Pa		STATE OF STATE OF	es	Down Time Codes	tions	Special Notes / Instructions	Specia
Ċ										ROUTING:
D										
	\									
	200			16						
	2									
	1 ()									
					6		+	Smr.	30	11/91/16
Scrap Scrap		Notes		Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
Control and Control	では、これは、これは、これは、これが、これには、これには、これには、これには、これには、これには、これには、これには	子の一方式の一方式の	AND THE PROPERTY OF THE PARTY O	Tartification of the same	できませるのでは	Control of		があるのではないのかのから	The state of the s	THE SHEET
	Thru- put/8hrs	Hr	Pcs./Hr		Cycle Time	Setup Hrs.	- S		Mach. No.	
							Do not require traceability.	Do not requi	Caps/Plugs I	Caps
						by "Lot Number	Located on the bag followed by "Lot Number."	ocated on t	Snap Rings	Snap
					e box label.	and date on th	Use their work order number and date on the box label.	Jse their wo	Flare Tubes	Flare
		BRZ00			letter "M."	tarting with the	Located on the spool label, starting with the letter "M."	ocated on t	Copper Tubing	Coppe
ò	1-01-ws	CUTU-0-1-1/8			word "heat."	ectly above the	Located on the box label, directly above the word "heat."	ocated on t	Brazing Rings	Brazii
A to		BRZ22			ox quantity.	ox label under b	Six digit no. located on the box label under box quantity.	six digit no.	Flare Nuts	Flar
-B	いったところう	CUTU-42-5/32				/ Numbers	Distinguishing Traceablity Numbers	Distingui		
		9-2.5-34	Ī				1		Order Qty	Ord
	No(s)	Component(s)		LC.	devices, LLC		400154 400 WOO	.400	Order No.	Ord
ility	Heat Lot/Traceability)]]]]		11000		000 000 0000	