									ing	6 Meeting			
	,	•							ing	5 Training			
	1001	100							ō	4 FAIR			
,	Notes /)	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	 Mainter Tooling 			
			nspection Record	First Part Ir					Down Time Codes		ctions	Special Notes / Instructions	Specia
													ROUTING:
	¢												
	Ö												8.
		310	Ö										8
		3	2	2.									
									24				
						~	DAYS	5 20	7	6	Colles	70	4116
	0					۵	3	3			3	1	2 1 2
Code	Sciap		140100			Code					(1
Scrap	Corne	The state of the s	Notes	TO STATE OF THE PARTY OF THE PA		Down Time	Down Time	Cum. Total	Total Pcs. Cu	Total	Prod Hrs.	Emp. Name	Date
The second second		put/8hrs					lime		nis.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
			CPI3						ceability.	מווים	no liot ledalle ti aceapility.	caps/ rugs	0
			L-RING	47.				Lot Number.	Located on the bag followed by Lot Number.	n the bal	Located o	Cans/Plugs	Card
			DR445				יייייייייייייייייייייייייייייייייייייי	ממנכ סוו נוופ	יבי וימוווסכו מווי	2 +6 2 6 2	l postod o	Dispersion of	6
			DD772				hov lahel	date on the	Use their work order number and date on the hox lahel	work ord	Use their	Flare Tubes	Flare
			CUTU-1 875-1/2	2			etter "M."	ng with the l	Located on the spool label, starting with the letter "M."	n the spo	Located o	Copper Tubing	Coppe
			BRZ04				vord "heat."	above the w	Located on the box label, directly above the word "heat."	n the box	Located o	Brazing Rings	Brazir
			CUTU-17-3/16	C.			ox quantity.	bel under bo	Six digit no. located on the box label under box quantity.	o. locate	Six digit n	Flare Nuts	Flar
			ᄃ					mbers	Distinguishing Traceablity Numbers	guishing	Disting		
			SF403-3-3/16	SF						850		Order Qty	Ord
		No(s)	component(s)	<u></u>		LLC	devices, LLC	4		399808		Order No.	Ord
	ceability	Heat Lot/Traceability)			200		17F	S40333/16-1-17F	S4033	Part No.	Pa