BRAZING PRODUCTION RECORD			Special Notes / Instructions	ROUTING:		1		1				1	Date Emp.		Mac	Caps/Plugs	Snap Rings	Flare Tubes	Copper Tubing	Brazing Rings	Flare Nuts		Order Qty	Oldel No.
ON RECORD			/ Instruction		+	+					1	S	ame	- t- 11	Mach. No.				_	-	Six		_	
	б 57	4 3 2 1	IS										Prod Hrs.			not requ	ated on	their wo	ated on	ated on	digit no.	Distingu		39
	Training Meeting	Maintenance Tooling Setup FAIR	Down Time Codes									60	Total Pcs.			Do not require traceability.	Located on the bag followed by "Lot Number."	Use their work order number and date on the box label.	Located on the spool label, starting with the letter "M."	Located on the box label, directly above the word "heat."	Six digit no. located on the box label under box quantity.	Distinguishing Traceablity Numbers	10	398930
			Codes										Cun		Setup	ķ	red by "Lo	ber and	l, startin	directly a	e box lab	olity Num		
		Date Part Submitted											Cum. Total				ot Number	date on th	g with the	above the	el under b	bers		
		Time Of Day											Down Time		Cycle			e box label.	letter "M."	word "heat.	ox quantity.			devices, LLC
		Approved Yes / No											Down Time Code	A CONTRACTOR OF THE PERSON OF						п				LLC
		Mtrl Check												Contraction of the Contraction o										
			First Part In		1				ă.						Pcs./Hr								11	
		Inspector	Inspection Record										Notes	Service of Author								C-RING	1103-24-1/4	componental
						5	1)-0	5						put/anrs	Thru-								الأد	
		Notes				23	5	10								3						N/A	30/1905	No(s)
				<	P								Scrap											
													Scrap Code											