Test Form 11/4/15	Te										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										2000		A CONTRACTOR OF THE CONTRACTOR	
										4 FAIR 5 Training			
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 			
			t Inspection Record	First Part Ir					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	Þ												
	>												
		Ş											
	7.	K 1											
	Ç	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\											
		. =											
										2		SB	4/4
Scrap Code	Scrap		Notes		Associ	Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs		res./nr			Time		Hrs.			MING.	
		Thru-		7			Cycle		Setup			No.	
									X	Do not require traceability.	Do not requ	Caps/Plugs	Сар
							a	ot Number.	ved by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
							box label.	date on the	nber and	Use their work order number and date on the box label	Use their w	Flare Tubes	Flare
							etter "M."	g with the l	ર્ગ, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
							vord "heat."	above the w	directly.	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
							ox quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no	Flare Nuts	Flar
	30140766	20	J-RING					nbers	blity Nun	Distinguishing Traceablity Numbers	Disting		
	NIA		501-4-1/4	ر.						2		Order Qty	Ord
	No(s)		Component(s)	, Cor		ררכ	devices, LLC	THE COLOR		395967	35	Order No.	Ord
	Heat Lot/Traceability	Heat Lo		,			1			501-4-1/4-R	501-	Part No.	Pa