Test Form 11/4/15	Test F									ORD	BRAZING PRODUCTION RECORD	BRAZING PR
									Training Meeting	6		
									FAIR	4		
					C. C.	100/100			Setup	ω ι		
	Notes		Inspector	Rev Letter	Mtrl	Approved	Time Of Day	Date Part Submitted	Maintenance Tooling	2 1		
			rt Inspection Record	First Part In				S	Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
	1											
		1										
	600											
	2	5										
	5											
					T				+			
									_			
									ىو		88	12/21
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					Time	Hrs.				
		Thru-		Pcs./Hr			Cycle	Setup	Se		Mach. No.	
									Do not require traceability.	Do not requir	Caps/Plugs	Cap
							.=	y "Lot Number	Located on the bag followed by "Lot Number."	Located on th		Snai
							e box label.	and date on the	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
							letter "M."	irting with the	Located on the spool label, starting with the letter "M."	Located on th	Copper Tubing	Coppe
							word "heat."	ctly above the v	Located on the box label, directly above the word "heat."	Located on th	Brazing Rings	Brazii
							ox quantity.	x label under b	Six digit no. located on the box label under box quantity.	Six digit no. k	Flare Nuts	Flar
	3300	20293300	A-RING	,				Numbers	Distinguishing Traceablity Numbers	Distinguis		
	À	Z/A	A40							2	Order Qty	Ord
	No(s)	No	component(s)	Com		LLC	devices, LLC	7	952	394952	Order No.	Ord
	Heat Lot/Traceability	Heat Lot/T					200		)-R	A40-R	Part No.	Pai
	Me.											