											•		
	023									5 Training	10.1		
		-									S (1)		
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	3.5	 Maintenance Tooling 			
			t Inspection Record	First Part In					Codes	-		Special Notes / Instructions	Specia
	•												ROUTING:
	7												
	3	1 1		1									
	7												
				l									
	1												
),												
	\												
										1			
										00		SB	17/8
Scrap	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cui	Total Pcs.	Prod Hrs.	Emp. Name	Date
No. of the last		put/8nrs					IIIId			CHILDRANG AND TOTAL		_	
		Thru-		Pcs./Hr			Cycle	505	Setup			Mach. No.	
	L								ſŸ.	po not reduite traceability.	oo not redu	caps/riugs	Cap
								Lot Number.	wed by "I	Located on the bag followed by "Lot Number."	Located on		Snar
							box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w		Flare
							etter "M."	ng with the l	el, startir	Located on the spool label, starting with the letter "M."	Located on	970	Coppe
and the same							vord "heat."	above the w	, directly	Located on the box label, directly above the word "heat."	Located on		Brazii
							ox quantity.	bel under bo	ne box lal	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		20151104	L-RING					nbers	blity Nur	Distinguishing Traceablity Numbers	Distingu		
		ZVA	L3/4							60		Order Qty	Ord
		No(s)	Component(s)	Con		ררכ	devices, LLC	H		393358	39	Order No.	Ord
	ility	Heat Lot/Traceability					1			L3/4-R	Б	Part No.	Ра