lest Form 11/4/15	lest										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										5 Training			
										3 Setup			
	3.	Notes	Inspector	Rev Letter	Check	Approved Yes / No	Time Of Day	Date Part Submitted	ro	<ol> <li>Maintenance</li> <li>Tooling</li> </ol>			
			t Inspection Record	First Part I					Codes	Down Time Codes	Instructions	Special Notes / Instru	Speci
													ROUTING:
	9	10 1											
		17900	To the second										
		2	<u>~</u>										
	_		one for	Durned	17C/	1				1	20 mias	CS	11/30
Code	Scrap	t	Notes		0	Down Time Code	Down Time	Cum. Total	Cr Cr	Total Pcs.	Prod Hrs.	Emp. Name	Date
Scran		CHARLES CONTRACTOR DESCRIPTION	は の できる		東京 からから		A STATE OF THE PARTY OF				はないというないので		
		Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
									<u> </u>	Do not require traceability.	Do not requ		Caps
							T.	ot Number.'	ed by "L	Located on the bag followed by "Lot Number."	Located on :		Snap
							box label.	date on the	ber and	Use their work order number and date on the box label.	Use their wo		Flare
							tter "M."	g with the le	l, startin	Located on the spool label, starting with the letter "M."	Located on :	oq .	Coppe
		3	CP14				ord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	SS	Brazin
		NIA	BRZ07				x quantity.	el under bo	e box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
		N/A	CUTU-0-5/8	C).				nbers	olity Nun	Distinguishing Traceablity Numbers	Distingu		
	782	3917	ASC-9							6		Order Qty	Orde
	2	No(s)				LC	devices, LLC	1		391782	39:	Order No.	Orde
	lity	Heat Lot/Traceability	Component(s)	Com			ontrol	3		ASC-9-5	AS	Part No.	Par