Test Form 11/4/15	Test Fo											JRD	BRAZING PRODUCTION RECORD	BRAZING PR
											6 Meeting			
ļ.		Notes		Inspector	Rev Letter	Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted	-000	 Maintenance Tooling 			
				Inspection Record	First Part In					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
														ROUTING:
	9												Đ	
	?		1											
		20												
		2												
	*	- 01												
-		>												
											00		SB	1/19
Scrap Code	Scrap			Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Irs	put/8hrs				E CONTRACTOR CONTRACTO	Time		Hrs.				
			Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
										<	Do not require traceability	Do not real		Caps
								п	ot Number.	ed by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
								box label.	date on the	iber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
								etter "M."	g with the lo	र्भ, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
								ord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
								x quantity.	pel under bo	e box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		20293300	20	A-RING					nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
		NIA		A15							8		Order Qty	Ord
		No(s)		component(s)	Con		LLC	devices, LLC	4		397392	35	Order No.	Ord
	ility	Heat Lot/Traceability	Неа	non-t(c)				ontrol			A15-R	A	Part No.	Pai