Test Form 11/4/15	Test F									RO	BRAZING PRODUCTION RECORD	BRAZING PRO
									Meering			
				1						n u		
			The state of the s	V						4. 1		
		A CONTRACTOR OF THE PERSON OF	+	2)	1	· AN	100	3 3 C C		. ω		
	Notes	No	Inspector	Rev Letter		-	Time Of Day	Submitted		2		
				5	Mtr	Approved	1	Date Part	Maintenance	1		
			First Part Inspection Record	First Part In				S	Down Time Codes	tions	Special Notes / Instructions	Special
												ROUTING:
	Ó											
	Ç											
									-			
		SUIT										
	*	22/										24
		700										
	4											
	2											
			ılı									
							1					
							0	45	72	/ REAL	7	MSett
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		STATE OF THE PARTY	STREET, STREET	The state of the s	NAME OF TAXABLE PARTY.					Control of the last	Control of the section and	
		Thru- put/8hrs		Pcs./Hr			Cycle Time	Setup Hrs.	Se		Mach. No.	
									Do Hot require traceability.	po not redu	caps/riugs	Cabs
							-	by For Nation	Possition included by Locindination.	Eocated of		0 00
							= 5	"I of Nimbo	the had followed t	ocated on t		Snan
						·="	າe box label	and date on th	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
						-	letter "M."	arting with the	Located on the spool label, starting with the letter "M."	Located on t	Copper Tubing	Coppe
			CP13			Ę. II	word "heat	ctly above the	Located on the box label, directly above the word "heat."	Located on t	Brazing Rings	Brazin
		1	BRZ23			у.	ox quantity	x label under b	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
			CUTU-1-1/2	ر د				Numbers	Distinguishing Traceablity Numbers	Distingu		
			SF405-5-1/4-1/2	SF40					72		Order Qty	Orde
	-	No(s)	Component(s)	Cor		, ררכ	devices, LLC	4	401810	*40.	Order No.	Orde
	eability	Heat Lot/Traceability					7		S405-5-1/4-1/2	S405-5	Part No.	Par