Test Form 11/4/15	Test For										CORD	BRAZING PRODUCTION RECORD	BRAZING PR
									Meeting	6 Mee			
		CD C	Y	V	•	144	101		. ~ .				
)	14	3	1	- 1		JI-15	ō	3 Setup			
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	 Mainter Tooling 			
			Inspection Record	First Part Ir					Down Time Codes	Do	uctions	Special Notes / Instructions	Specia
													ROUTING:
	7			82									
	1000	-											
	\C\												
	1			Ð									
	5/												
	`						,						
	Q						Ø	950	50	0 # J	0	4	2/2
Scrap Code	Scrap		Notes	٠		Down Time Code	Down Time	Cum. Total	Total Pcs. C		Prod Hrs.	Emp. Name	Date
		put/oills	Charles and the second									The state of the s	
		Thru-		Pcs./Hr			Cycle	ס	Setup	ň		Mach. No.	
	a.								dceability.	Do Horredalle Haceability.	ס ווסר	caps/ridgs	Car
							l e	"Lot Number.	Located on the bag followed by "Lot Number."	d on the b	Locate	Snap Rings	Snal
			CP13				box label.	d date on the	Use their work order number and date on the box label	eir work or	Use the	Flare Tubes	Flare
			BRZ05		1		etter "M."	ing with the l	Located on the spool label, starting with the letter "M."	d on the sp	Locate	Copper Tubing	Coppe
			BRZ01				vord "heat."	y above the v	Located on the box label, directly above the word "heat."	d on the b	Locate	Brazing Rings	Brazi
			CUTU-14-1/4	C			ox quantity.	abel under bo	Six digit no. located on the box label under box quantity.	it no. locat	Six digi	Flare Nuts	Flar
			CUTU-3-1/2	CL				ımbers	Distinguishing Traceablity Numbers	stinguishing	Dis		
	922	292	SF4-4-2							200		Order Qty	Ord
	No(s)		Component(s)	Cor		LLC	devices, LLC	THE STATE OF THE S		393776		Order No.	Ord
	Heat Lot/Traceability	Heat Lo							1	S4-4-2-14		Part No.	Pa