Test Form 11/4/15	Tes										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
					Check	Yes / No		Submitted		2 Tooling 3 Setup			
	Notes		Inspector	Rev Letter	Mtrl	Approved	Time Of Dav	Date Part	nce				
			First Part Inspection Record	First Part In					ne Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	7												
	5												
	l L												
		), ,	5										
		S											
		Ą											
			)										
		8											
										120		SB	8/8
Scrap Code	Scrap	1	Notes		78-25	Down Time Code	Down Time	Cum. Total	Сп	Total Pcs.	Prod Hrs.	Emp. Name	Date
The state of the s	*	pur/oiiis			No. of the last of						Marie Marie Control	Printed a separate	
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
									ility.	Do not require traceability.	Do Hot Ledi	caps/riugs	Cap
					J		. =	Located on the bag followed by "Lot Number."	owed by "	the bag foll	Located on	Snap Rings	Snap
					1		e box label.	Use their work order number and date on the box label	umber and	ork order nu	Use their w	Hare Tubes	Hare
							letter "M."	Located on the spool label, starting with the letter "M."	bel, starti	the spool la	Located on	Copper Tubing	Coppe
					L		vord "heat."	Located on the box label, directly above the word "heat."	el, directly	the box lab	Located on	Brazing Rings	Brazir
							ox quantity.	Six digit no. located on the box label under box quantity.	the box la	located on	Six digit no.	Flare Nuts	Flar
	N/A	2	G-RING	•				mbers	eablity Nu	Distinguishing Traceablity Numbers	Distingu		
	395368	دن	705-15-3/16	705						120		Order Qty	Ord
	No(s)		omponent(s)	Con		LLC	devices, LLC	1		399741	39	Order No.	Ord
	Heat Lot/Traceability	Heat Lo					ont no			705-15-3/16-6	705-1	Part No.	Pai