Test Form 11/4/15	Test Fo										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										l A			
										4 FAIR			
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Ф	 Maintenance Tooling 			
			First Part Inspection Record	First Part I					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	9												
	P												
			-										
		0	7									•	
										ė			
					1		_						
	9									90		56	1730
Code	Scrap		Notes			Code	Down Time	Cum. Total	5	Total Pcs.	Prod Hrs.	Emp. Name	Date
Coran			STANDED TO SERVICE STANDARDS	STATE OF THE PERSON NAMED IN	The substitute of		Service applications	CHANNE INCIDENT	No. of Street, or other Persons and Street, o	日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日	のは、日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日		
	a	Thru- put/8hrs		Pcs./Hr			Cycle Time	***	Setup Hrs.			Mach. No.	
									ŢŸ.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
					Ц		=	Lot Number.	wed by "	Located on the bag followed by "Lot Number."	Located on		Snap
					1		box label.	d date on the	nber and	Use their work order number and date on the box label	Use their w	Flare Tubes	Flare
							etter "M."	ng with the I	el, starti	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
					L		vord "heat."	above the v	, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
							ox quantity.	bel under bo	າe box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
		HOLLSTOR	L-RING					mbers	blity Nu	Distinguishing Traceablity Numbers	Distingu		
		395385	S403-3-1/4	Š					لـــا	20		Order Qty	Ord
		No(s)	Component(s)	COL		LLC	devices, LLC	H		395429	39	Order No.	Ord
	ility	Heat Lot/Traceability	anonout(c)	2			ontrol			S403-3-1/4-R	S403	Part No.	Par