Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PF
										6 Meeting			
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	ıce	<ol> <li>Maintenance</li> <li>Tooling</li> </ol>			
			First Part Inspection Record	First Part In					ne Codes	Down Time Codes	ctions	Special Notes / Instructions	Speci
													ROUTING:
	I												
	>												
		1											
	1	Ü	7										
		5											
				ad									
				ų,									
										2		CIC	2/4
Scrap Code	Scrap		Notes		300	Down Time Code	Down Time	Cum. Total	0	Total Pcs.	Prod Hrs.	Emp. Name	Date
		bar, om s				The second second						The state of the s	
		Thru-		Pcs./Hr			Cycle	· '5	Setup			Mach. No.	
		d.			_				ility.	Do not require traceability.	Do not req	Caps/Plugs	Сар
							's	Located on the bag followed by "Lot Number."	owed by	the bag foll	Located on	Snap Rings	Sna
							box label.	Use their work order number and date on the box label.	ımber an	ork order nu	Use their w	Flare Tubes	Flar
							etter "M."	Located on the spool label, starting with the letter "M."	bel, start	the spool la	Located on	Copper Tubing	Copp
						EII	vord "heat."	Located on the box label, directly above the word "heat."	el, directi	the box lab	Located on	Brazing Rings	Brazi
		N/A	G17				ox quantity.	Six digit no. located on the box label under box quantity.	the box l	. located on	Six digit no.	Flare Nuts	Fla
		NA	G-RING					imbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
	_[	397064	702-4-3/8	7						4		Order Qty	Orc
		No(s)	Component(s)	G		LLC	devices, LLC			399882	35	Order No.	Oro
	lity	Heat Lot/Traceability		)						702-4-3/8-17	702	Part No.	Pa