Tot Form 14 1/45										
						_	MEETING			
		Î	A				Training	5 T		
	(- [FAIR			
	Pari A	7	1	H	Mail	アナイン	Setup			
, K	Notes	tter Inspector	Check Rev Lett	Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2 1 √		
		First Part Inspection Record					Down Time Codes		Special Notes / Instructions	Specia
										ROUTING:
										DOLLTING.
Ż										
?										
	~						_			
	1.5									
	これで									
			1							
	5									
							24			
										1 1
							/	15 MIN)	· CS	11/17/15
Scrap Code		Notes		Down Time Code	Down Time	Cum. Total	Total Pcs. Ci	Prod Hrs. To	Emp. Name	Date
Section and Section 2015			不可以 は 大きまへき				Mary and Mary and American	A SOCIETY OF THE PERSON OF THE		
	Thru- put/8hrs		Pcs./Hr		Cycle Time	0	Setup Hrs.		Mach. No.	
							aceability.	Do not require traceability.	Ī	Caps/Plugs
						Lot Number.	ag followed by "	Located on the bag followed by "Lot Number."		Snap Rings
		CFT3			box label.	date on the	der number and	Use their work order number and date on the box label.		Flare Tubes
	7	COAL			itter ivi.	ng with the is	ool label, starti	Located on the spool label, starting with the letter lyi.		Copper Tubing
22/72	1/4	BB777			0.00	ייון אף יון	Ox label, directly	Located of the box laber, directly above the work incur		Brazing Kings
	NIA	BRZ01			ord "heat "	w adt avode	ov label directly	acatad an the h		7 1010
	M86741	CUTU-0-5/32	0		x quantity.	bel under bo	ed on the box la	six digit no located on the box label under box quantity.		Elaro Nute
	NIA	CUTU-0-1/2				mbers	Distinguishing Traceablity Numbers	Distinguishing		
	390/22	4-2.5-12						1	Otv	Order Qtv
	No(s)			C	devices, LLC	P 7		390622	No.	Order No.
ility	Heat Lot/Traceability	Component(s)	ი		ontrol		4-B	S4-2.5-12-24-B	No.	Part No.