Part No.	Þ	A30-R			1			,		Heat Lot	Heat Lot/Traceability		
Order No.	39	391774		H	devices, LLC	LLC		Com	omponent(s)		No(s)		-
Order Qty		12							A30	2	/A		
	Disting	Distinguishing Traceablity Numbers	lity Numb	ers				1	A-RING	7	NA		
Flare Nuts	Six digit no.	Six digit no. located on the box label under box quantity.	box labe	l under bo	ox quantity.				,				
Brazing Rings	Located on	Located on the box label, directly above the word "heat."	directly ab	ove the v	vord "heat."								
Copper Tubing	Located on	Located on the spool label, starting with the letter "M."	, starting	with the I	etter "M."								
Flare Tubes	Use their w	Use their work order number and date on the box label.	per and da	ate on the	box label.								
Snap Rings	Located on	Located on the bag followed by "Lot Number."	ed by "Lot	t Number.									
Caps/Plugs	Do not requ	Do not require traceability.											
	Andrew State of	THE SHAPE OF THE STREET, SAN	THE RESERVE	ALPER CALIFORNIA CONTROL					A STATE OF THE PARTY OF THE PAR				
Mach. No.	•		Setup Hrs.		Cycle Time			Pcs./Hr		Thru- put/8hrs			
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum.	Cum. Total	Down Time	Down Time Code			Notes		Scrap	p Scrap Code	ਰੌਂ ਚ
11/30 56		12											
		ig.											
											7		
										201		+	
										7.7.0) a		
										5.	2	\	
											t		
ROUTING:													
Special Notes / Instructions	ructions	Down Time (Codes					First Part In	First Part Inspection Record				
		Maintenance		Date Part		Approved	4						
				Submitted	Time Of Day	Yes / No	Check	Rev Letter	Inspector		Notes		
		3 Setup 4 FAIR											
		5 Training						_					
BRAZING PRODUCTION RE	CORD	e miccini.										Tool Form 44	1
BRAZING PRODUCTION RECORD	CORD											Test Form 11/4/15	14/15