						Special Notes / Instructions	ROUTING:											٧ <u>٧</u>	Date Emp	Ma		Caps/Plugs	Snap Rings	Flare Tubes	Copper Tubing	Brazing Rings	Flare Nuts		Order Qty	Order No.	Part No.
						s / Instructi		_										SB	Emp. Name	Mach. No.					_	-			_		
	יט ת	4	ω	2 +		ons													Prod Hrs.		R SPECIAL COMPANY	o not requ	cated on t	se their wo	cated on t	cated on t	x digit no.	Distingu		39	2803A
			. Tooling	1	Down Time Codes											=	T	Total Pcs.		Control of the least of the lea	Do not require traceability.	Located on the bag followed by "Lot Number."	Use their work order number and date on the box label	Located on the spool label, starting with the letter "M."	Located on the box label, directly above the word "heat."	Six digit no. located on the box label under box quantity.	Distinguishing Traceablity Numbers	4	396518	2803A-18-3/16	
			_	_		odes													Cum. Total	Setup Hrs.	Contract of the least		ed by "Lot	per and da	, starting	directly ab	box labe	lity Numb			
				Submitted	Data Dart														Total				Number.	ate on the	with the l	ove the w	l under bo	ers		TY.	
				Time Of Day															Down Time	Cycle Time			н	box label.	etter "M."	ord "heat."	x quantity.			devices, LLC	201
				Yes / No	2000														Down Time Code	į.										LLC	
L				Check	п																										
		_		Rev Letter		First Part In														Pcs./Hr							4	2803,	DC	Con	
				Inspector	openion income	Inspection Record													Notes								A-KF003	2803A-18-3/16-0	DCN516-HT	omponent(s)	nonont(-)
										(1, ()	-	3	=							Thru- put/8hrs								396		וופמר	Heat Lo
				Notes						,			0														NA	396018	NIA	No(s)	Heat Lot/Traceability
								Ò	P										Scrap												4
																			Scrap Code												