Test Form 11/4/15	v									RD	BRAZING PRODUCTION RECORD	BRAZING PR
								-	0			
									Meeting	б (
									FAIR	4. 1		
	1								Setup	3		
	Notes		Inspector	Rev Letter	Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2		
			rt Inspection Record	First Part Ir					Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
	Ž	1										
	>	1 25										
		1										
	_	111										
		•										
	1											
					5							
7				7								
									50		SB	4/1
p Scrap Code	Scrap		Notes		A-11	Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8nrs					IIme	•	nis.			
		Thru-		Pcs./Hr			Cycle	- d	Setup		Mach. No.	
	3								e traceability.	Do not require traceability.	Caps/Plugs	Cap
							· a	"Lot Number.	Located on the bag followed by "Lot Number."	Located on th		Snar
				-	1		e box label.	nd date on the	Use their work order number and date on the box label.	Use their worl	Flare Tubes	Flare
							etter "M."	ting with the I	Located on the spool label, starting with the letter "M."	Located on th	Copper Tubing	Coppe
							vord "heat."	ly above the v	Located on the box label, directly above the word "heat."	Located on th	Brazing Rings	Brazi
							ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. lo	Flare Nuts	Flar
	20151104	3016	L-RING					umbers	Distinguishing Traceablity Numbers	Distinguisl		
	395408	395	S403-4-1/4	Z.						50	Order Qty	Ord
	No(s)		Lomponent(s)	G		LLC	devices, LLC	H	49	395549	Order No.	Ord
	Heat Lot/Traceability	Heat Lo		2			O T		1/4-R	S403-4-1/4-R	Part No.	Pai