		THE COLUMN TWO IS NOT	12073 (279)	TO THE			Training Meeting	6 5		
		All I	OK A	XEX S	8:25	12-1-15	Setup	4 3 1		
	Notes	tter Inspector	Mtrl Rev Letter	Approved	Time Of Day	Date Part Submitted	Maintenance	1		
		art Inspection Record	First Par	-	-1 T. V.		Down Time Codes	tions	Special Notes / Instructions	Specia
										ROUTING:
9										
P	I									
	7,									
	200									
-	1910									
							_	10 min	CS	12-1-15
Scrap Scrap Code		Notes		Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
				AND REAL PROPERTY.				- T		
	Thru- put/8hrs	Hr	Pcs./Hr		Cycle Time	s. up	Setup Hrs.		Mach. No.	
	2						Do not require traceability.	Do not requir	Caps/Plugs I	Caps
	*				- =	/ "Lot Number	Located on the bag followed by "Lot Number."	ocated on th		Snap
					e box label.	nd date on the	Use their work order number and date on the box label.	Jse their wor	Flare Tubes	Flare
					letter "M."	rting with the	Located on the spool label, starting with the letter "M."	ocated on th	Copper Tubing	Coppe
					word "heat."	tly above the v	Located on the box label, directly above the word "heat."	ocated on th	Brazing Rings	Brazir
	367	CUTU-24-3/16			ox quantity.	label under b	Six digit no. located on the box label under box quantity.	ix digit no. lc	Flare Nuts	Flare
	w	BRZ04				lumbers	Distinguishing Traceablity Numbers	Distinguis		
_ [391986	4-3-9						1	Order Qty	Orde
•	No(s)	Component(s)		LLC	devices, LLC	A T	386	391986	Order No.	Ord
~	Heat Lot/Traceability				1		-24	4-3-9-24	Part No.	Par