											1	1	DO A TIME DE COME DE COME
	Notes	95.11.10	Inspector	Rev Letter			11/180	Submitted	la Co	l .			
			t Inspection Record	First Part In	Mtri	Approved	A PROPERTY.	Date Part	Codes	Down Time Codes  Maintenance		Special Notes / Instructions	Specia
				A STATE OF S									ROUTING:
0	***												
	SS	2.											1
	2/4	5.	•										
	5				$\dagger$								
								I					
							0	17	r	14	a mes	U	415/16
		1					0	3	S	509	2,5	ye	3/9/11
Scrap Scrap	Ş		Notes			Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
	144	Thru- put/8hrs	18	Pcs./Hr	3 MIN	3.1	Cycle Time	30 MIN	Setup Hrs.	H2		Mach. No.	
									<i>'</i> .	Do not require traceability.	Do not requ	3	Caps
							н	ot Number.	ed by "Lo	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
							box label.	date on the	ber and o	Use their work order number and date on the box label	Use their w		Flare
							etter "M."	with the l	l, starting	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						=	vord "heat.	bove the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
			BRZ00				ox quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
			CASC-11					bers	lity Num	Distinguishing Traceablity Numbers	Distingu		
			ASC-11							20		Order Qty	Orde
	No(s)		Component(s)	Cor		LLC	devices, LLC	H		403259	40	Order No.	Ord
	Heat Lot/Traceability	Heat Lot					7			ASC-11-7	ASO	Part No.	Par