Test Form 11/4/15	Test F									RD	BRAZING PRODUCTION RECORD	BRAZING PRO
				45					Meeting	6 (		
									FAIR			
	. vs	Notes	Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted	Tooling Setup	<b>3 2 ⊢</b>		
			Inspection Record	First Part Ir					Down Time Codes		Special Notes / Instructions	Specia
												ROUTING:
	7											
			V.	7								
			1									
			110	>								
									Ö		SB	2/8
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs. Cu	Prod Hrs. To	Emp. Name	Date
		put/8hrs		PCS./Hr			Time		Hrs.		MIGCH. NO.	
		Thru-		7		- Company of the Comp	Cycle		Setup	And the second second	Mach No	
									raceability.	Do not require traceability.	Caps/Plugs [	Caps
							ä	Lot Number.	Located on the bag followed by "Lot Number."	ocated on the		Snap
							box label.	date on the	Use their work order number and date on the box label.	Jse their work	Flare Tubes	Flare
							etter "M."	ng with the I	Located on the spool label, starting with the letter "M."	ocated on the	Copper Tubing	Coppe
V-H			1				vord "heat."	above the v	Located on the box label, directly above the word "heat."	ocated on the	Brazing Rings	Brazir
							ox quantity.	bel under bo	Six digit no. located on the box label under box quantity.	ix digit no. loca	Flare Nuts	Flan
		30140766	J-RING					mbers	Distinguishing Traceablity Numbers	Distinguishi		
		399853	502-8-3/16	50						10	Order Qty	Orde
		No(s)	Component(s)	Con		LLC	devices, LLC	H		399726	Order No.	Ord
	oility	Heat Lot/Traceability		,			, , , , , , , , , , , , , , , , , , , ,	1	6-R	502-8-3/16-R	Part No.	Par