)	BBAZING BBODI ICTION BECOME	77110
			×.					FAIR Training Meeting	4 FAIR 5 Train 6 Meet			
0000	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling Setup				
		t Inspection Record	First Part I					Down Time Codes	Do	ctions	Special Notes / Instructions	Specia
												ROUTING:
7												
	10 5											
	12-1-15							1				
						•						
									+			
								C			CW	2-16-18
Scrap Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.		Prod Hrs.	Emp. Name	Date
	put/8hrs					Time	S.	Hrs.				
	Thru-		Pcs./Hr			Cycle	du	Setup			Mach. No.	
								Do not require traceability.	require t	Do not i	Caps/Plugs	Caps
						Ē	/ "Lot Number	Located on the bag followed by "Lot Number."	on the k	Located	Snap Rings	Snap
		1				e box label.	nd date on the	Use their work order number and date on the box label.	ir work o	Use the	Flare Tubes	Flare
						letter "M."	rting with the I	Located on the spool label, starting with the letter "M."	on the s	Located	Copper Tubing	Coppe
						word "heat.	tly above the v	Located on the box label, directly above the word "heat."	on the k	Located	Brazing Rings	Brazin
	10 La	C-RING				ox quantity.	label under b	Six digit no. located on the box label under box quantity.	no. loca	Six digit	Flare Nuts	Flar
		C15					lumbers	Distinguishing Traceablity Numbers	inguishir	Dist		
	こず	1102-15-1/4	1:						5		Order Qty	Ord
	No(s)	Component(s)	6		ררכ	devices, LLC	C)	•	394331		Order No.	Ord
ility	Heat Lot/Traceability									-	1 1 1 1 1 1 1	