├ ───── ───────────────────────────────				Г			
Notes Scrap Notes Notes Notes Notes			1	5 Iraining 6 Meeting			
Notes Scrap Notes Scrap	Check Rev Letter	Time Of Day Approved Yes / No	Submitted 12-10-15	MaintenanceToolingSetupFAIRTraining	. N. (0) N		
Thru- put/8hrs Scrap	First Par				-	Special Notes / Instructions	Specia
Thru- put/8hrs Scrap							ROUTING:
Notes Scrap							
Thru- put/8hrs Scrap							
Thru- put/8hrs Scrap							
Thru- put/8hrs Scrap							
Thru- put/8hrs Scrap							
Thru- put/8hrs Scrap							
Thru- put/8hrs Scrap							
Thru- put/8hrs Scrap							
Thru- put/8hrs Scrap		4	+			ç	of the
Thru-put/8hrs Scrap		2	7	7	7	1	12/2/10
		Down Time Code	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Time	Hrs.				
	Pcs /Hr	Cycle	Setup			Mach. No.	
				Do not require traceability.	Do not requ	Caps/Plugs	Caps
		i a	Located on the bag followed by "Lot Number."	the bag followed	Located on	Snap Rings	Snap
		e box label.	Use their work order number and date on the box label.	ork order numbe	Use their wo	Flare Tubes	Flare
		letter "M."	Located on the spool label, starting with the letter "M."	the spool label,	Located on	Copper Tubing	Coppe
CP13	CP	word "heat."	Located on the box label, directly above the word "heat."	the box label, di	Located on	Brazing Rings	Brazir
BRZ03	BR	ox quantity.	Six digit no. located on the box label under box quantity.	located on the b	Six digit no.	Flare Nuts	Flan
CUTU-1-1/2	CUTU		ty Numbers	Distinguishing Traceablity Numbers	Distingu		
SF404-9-3/16 SHON-9-3/C	SF404-			2		Order Qty	Ord
Component(s) No(s)	compo	devices, LLC	Ť	391670	39	Order No.	Ord
Heat Lot/Traceability)			S404-9-3/16	S404	Part No.	Pai