Test Form 11/4/15	Test Fo										ORD	BRAZING PRODUCTION RECORD	BRAZING PRO
				8						5 Training 6 Meeting			
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	nce	 Maintenance Tooling 			
			t Inspection Record	First Part In					Down Time Codes	Down Ti	ctions	Special Notes / Instructions	Specia
													ROUTING:
	7												
			-										
			To B										
			7/10										
		+	5										
									+				
Scrap Code	Scrap	2	Notes	2		Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
	The second second	bar, cimo						And Sales of the	Statement of the				
		Thru-		Pcs./Hr			Cycle	0	Setup Hrs.			Mach. No.	
			1						oility.	Do not require traceability.	Do not req	Caps/Plugs	Caps
					Į.			Located on the bag followed by "Lot Number."	lowed by	the bag fo	Located or		Snap
							e box label.	Use their work order number and date on the box label.	number an	vork order r	Use their v	Flare Tubes	Flare
							etter "M."	Located on the spool label, starting with the letter "M."	abel, start	the spool I	Located or	Copper Tubing	Coppe
							vord "heat."	Located on the box label, directly above the word "heat."	pel, directl	the box lat	Located or	Brazing Rings	Brazir
							ox quantity.	Six digit no. located on the box label under box quantity.	the box l	. located or	Six digit no	Flare Nuts	Flar
								ımbers	ceablity Nu	Distinguishing Traceablity Numbers	Disting		
			CUTU-36-5/32	CU						150		Order Qty	Ord
	7	No(s)	Component(s)	Cor		רכ	devices, LLC	THE STATE OF THE S		401210	4	Order No.	Ord
	oilitv	Heat Lot/Traceability	**************************************	,						CUTU-36-5/32-B	CUTU	Part No.	Pai