	6					6 У .		
Notes	Rev Letter Lnspector	Yes / No Check	Time Of Day	Submitted	2 Tooling 3 Setup 1 FAIR	4 3 2 1		
	First Part Inspection Record				10,510		Special Notes / Instructions	Specia
								ROUTING:
	210							
\ <u>\</u> \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \								
,								
					_			
			1/2 hr	77	43	W	JUS	8618
	Notes	Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Da
put/8hrs	Pcs./Hr pu		Time	Hrs.			Mach. No.	
							A COUNTY OF THE PARTY OF THE PA	
					Do not require traceability.	o not requ	Caps/Plugs I	Caps
			~ _	by "Lot Number	Located on the bag followed by "Lot Number."	ocated on		Snap
	CP13		e box label.	and date on th	Use their work order number and date on the box label.	Jse their w	Flare Tubes	Flare
	BRZ23		letter "M."	tarting with the	Located on the spool label, starting with the letter "M."	ocated on	Copper Tubing	Coppe
	CUTU-2-1/2		word "heat."	ectly above the	Located on the box label, directly above the word "heat."	ocated on		Brazii
	BRZ04		ox quantity.	ox label under b	Six digit no. located on the box label under box quantity.	six digit no.	Flare Nuts	Flar
	CUTU-6-3/16-B			/ Numbers	Distinguishing Traceablity Numbers	Distingu		
	SF4-3-3	1	10 10	1	40		Order Qty	Ord
No(s)	Component(s)	rc C	devices, LLC	八八	405236	40	Order No.	Ord
Heat Lot/Traceability					0.000	01.0		Fa