Test Form 11/4/15	Test										ORD	BRAZING PRODUCTION RECORD	BRAZING PF
										6 Meeting			
								-					
	es	Notes	Inspector	Rev Letter	Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted	ř	 Maintenance Tooling 			
			First Part Inspection Record	First Part In					e Codes	Down Time Codes	ctions	Special Notes / Instructions	Speci
													ROUTING:
	B												
		1000											
		137											
		76											
				,.									
										H		88	08/1
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Ç	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs		Pcs./Hr			Cycle		Hrs.			Mach. No.	
				ACTION OF THE PERSON					·				
									ty.	Do not require traceability.	Do not requ	Caps/Plugs	Сар
							• =	Lot Number.	wed by "	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
							box label.	d date on the	nber and	Use their work order number and date on the box label.	Use their w		Flare
							etter "M."	ng with the I	el, starti	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
							vord "heat."	above the v	, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
							ox quantity.	bel under bo	ne box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		20060667	E-RING					mbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
		396735	902-12-1/4	90						4		Order Qty	Ord
	5	No(s)	Component(s)	Con		LLC	devices, LLC	H		397542	39	Order No.	Ord
	bility	Heat Lot/Traceability					200			902-12-1/4-R	902-1	Part No.	Pa