Test Form 11/4/15	Test F									RD	BRAZING PRODUCTION RECORD	BRAZING PRO
					in in				Meeting	6		
									Training	5 4		
									Setup			
	-	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2		
			t Inspection Record	First Part Ir					Down Time Codes		Special Notes / Instructions	Specia
												ROUTING:
	P											
		<i>Y</i>	0									
		1255.	)									
		) _ (										
		0)1										
									8			
						1						
									49		SS	2/1
Scrap	Scrap	0.20	Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					IIme	3.	l list			
		Thru-		Pcs./Hr			Cycle	, d	Setup		Mach. No.	
									e traceability.	Do not require traceability.	Caps/Plugs	Caps
							i a	"Lot Number	Located on the bag followed by "Lot Number."	ocated on th		Snap
							e box label.	nd date on the	Use their work order number and date on the box label.	Jse their wor	Flare Tubes	Flare
							letter "M."	ting with the I	Located on the spool label, starting with the letter "M."	ocated on th	Copper Tubing	Coppe
						-	word "heat."	tly above the v	Located on the box label, directly above the word "heat."	ocated on th	Brazing Rings	Brazii
		ZA	G-RING				ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. lo	Flare Nuts	Flar
		N/N	G3					lumbers	Distinguishing Traceablity Numbers	Distinguis		
		2/2	702-9-3/16	7,						49	Order Qty	Ord
		No(s)	Component(s)	Col		ררכ	devices, LLC	H	36	398936	Order No.	Ord
	oility	Heat Lot/Traceability		Ā			7		/16-3	702-9-3/16-3	Part No.	Pai