Test Form 11/4/15	Test F									RD	BRAZING PRODUCTION RECORD	BRAZING PRO
									Meeting			
										л 4 п		
	37.7	Notes	Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted		» 2 L		
			First Part Inspection Record	First Part Ir	11			H			Special Notes / Instructions	Specia
												ROUTING:
				1								
	1						1					
	55.	1	1					ii				
	1											
	>											
				=								
									రు		SS	3/8
Scrap Code	Scrap		Notes		250	Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs		Pcs./Hr			Time	Hrs.	Ξ		Mach. No.	
		Thru-			THE REAL PROPERTY.		Cycle	Setup	Set			
		d							Do not require traceability.	Do not requi	Caps/Plugs	Caps
					I		. =	y "Lot Number.	Located on the bag followed by "Lot Number."	ocated on the	Snap Rings	Snap
							e box label.	and date on the	Use their work order number and date on the box label.	Jse their wo	Flare Tubes	Flare
							etter "M."	rting with the I	Located on the spool label, starting with the letter "M."	ocated on th	Copper Tubing	Coppe
						-	word "heat."	tly above the v	Located on the box label, directly above the word "heat."	ocated on th	Brazing Rings	Brazir
		NIA	G-RING	1980			ox quantity.	k label under bo	Six digit no. located on the box label under box quantity.	Six digit no. l	Flare Nuts	Flan
		NIA	G3					Numbers	Distinguishing Traceablity Numbers	Distinguis		
		39706	702-12-3/16	70					3	1.5	Order Qty	Ord
		No(s)	Component(s)	Cor		LLC	devices, LLC	Ŧ	399738	399	Order No.	Ord
	ility	Heat Lot/Traceability	Control of				7		702-12-3/16-3	702-12-	Part No.	Par