Test Form 11/4/15	Test F								ORD	BRAZING PRODUCTION RECORD	BRAZING PR
								Meeting			
			0	t			100		4.7		
			The latter	\ (t	YES L	10:35	2-8-16		ω		
	tes	Notes	Inspector	Mtrl Rev Letter	Approved M Yes / No Ch	Time Of Day	Date Part Submitted	Maintenance Tooling	2 1		
			t Inspection Record	First Par	П	THE STREET	H			Special Notes / Instructions	Specia
											NOOTING:
	Ċ				-						POLITING.
	V										
		(V								
		,	1								
			180								
			C/ /								
		,									
		5.			+						
	,					-					, , ,
	0					Ø	α	œ	20 MIN	245	2/18/16
Scrap Code	Scrap		Notes		Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs				Time	Hrs.		No. of the Control of	and the second second second	
		Thru-		Pcs./Hr		Cycle	Setup			Mach. No.	
						•		Do not require traceability.	Do not requ	Caps/Plugs	Caps
						î.e	Located on the bag followed by "Lot Number."	the bag follower	Located on t	Snap Rings	Snap
						e box label.	Use their work order number and date on the box label.	ork order numb	Use their wo	Flare Tubes	Flare
	3					etter "M."	Located on the spool label, starting with the letter "M."	the spool label,	Located on t	Copper Tubing	Coppe
			CP13			vord "heat."	Located on the box label, directly above the word "heat."	the box label, di	Located on t	Brazing Rings	Brazir
			BRZ23			ox quantity.	Six digit no. located on the box label under box quantity.	located on the	Six digit no.	Flare Nuts	Flar
	-	1/2/2	CUTU-1-1/2	C			ty Numbers	Distinguishing Traceablity Numbers	Distingui		
	۷		SF405-7-3/16	SF4				00		Order Qty	Ord
		No(s)	Component(s)	Con	5	devices, LLC	H	399770	399	Order No.	Ord
	ability	Heat Lot/Traceability)		7		S405-7-3/16	S405-	Part No.	Pai