								6 Meeting			
	1				0.73	3/12	- W - 170	4 FAIR			
	)		Check	Yes/No	N 100	Submitted		2 Tooling 3 Setup			
Notes	Inspector	Rev Letter	-	Approved	Time Of Dav	Date Part	nce				
	First Part Inspection Record	First Part					Down Time Codes	Down Tir	tions	Special Notes / Instructions	Special
											ROUTING:
7											
							1				
	C										
2/0/2	v.l										
2											
					,						,
					B	۲	01	ಬ	\$45 ms	U	21/149/8
Scrap	Notes		- e	Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date /
put/8hrs		F65/111			Time		Hrs.			Macil. Mo.	
Thru-		Dos /Hr			Cycle		Setup			Mach No	
							ility.	Do not require traceability.	Do not requ	`	Caps/Plugs
					=	ot Number.	Located on the bag followed by "Lot Number."	the bag foll	Located on		Snap Rings
	2				box label.	date on the	Use their work order number and date on the box label	ork order ni	Use their w	,	Flare Tubes
					etter "M."	with the le	Located on the spool label, starting with the letter "M."	the spool la	Located on	,	Copper Tubing
					ord "heat."	bove the w	Located on the box label, directly above the word "heat."	the box lab	Located on	Brazing Rings	Brazin
	BRZ04				x quantity.	el under bo	Six digit no. located on the box label under box quantity.	located on	Six digit no.	Flare Nuts	Flare
	CUTU-18-3/16	CU				bers	<b>Distinguishing Traceablity Numbers</b>	ishing Trace	Distingu		
	9-3-20							2		Qty	Order Qty
No(s)	Component(s)	6		LLC	devices, LLC			405072	40	r No.	Order No.
Heat Lot/Traceability	1	)			2	ı		9-3-2U-18	9-3-	INO.	Part No.