Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
		Notes	Inspector	Rev Letter	Check	Approved Yes / No	Time Of Day	Date Part Submitted	Ф	 Maintenance Tooling Setun 			
			t Inspection Record	First Part I	11		MIN N		Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	7												
)		Z.										
		To	7										
		33/4											
				11									
		621											
												88	2/23
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cui	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					Time		Hrs.				
113		Thru-		Pcs./Hr			Cycle		Setup	Š		Mach. No.	
									[Ÿ	Do not require traceability.	Do not requ	Caps/Plugs	Caps
					1		=	ot Number.	ved by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
					1		box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
							etter "M."	ng with the le	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
							ord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazii
							x quantity.	bel under bo	e box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		N/A	G-RING					nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
		N/A	GR5		l .					1		Order Qty	Ord
		No(s)	component(s)	COL		LC	devices, LLC			401580	40	Order No.	Ord
	<	Heat Lot/Traceability	anonon+(c)	60			ont not			GR5-R	9	Part No.	Pai