Test Form 11/4/15	Test Fo										)RD	BRAZING PRODUCTION RECORD	RAZING PRO
						ı				6 Meeting			
		D (CO) (P) (1)	Value 1		Check	Yes / No	5	Suprillitien		3 Setup			
		Notes	Inspector			Approved	Time Of Day	Date Part					
			Inspection Record	First Part In					Codes	Down Time Codes	ctions	Special Notes / Instructions	Special
													ROUTING:
	Z												
			4										
		1	2										
													1
										175		SB	3/8
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
		but/oills					IIIIIC		111.50				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
									×	Do not require traceability.	Do not requ	Caps/Plugs	Caps,
						19	=	ot Number.	ved by "L	Located on the bag followed by "Lot Number."	Located on		Snap
							box label.	date on the	iber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
							etter "M."	g with the le	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Copper
							vord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazin
	1	30060667	E-RING				x quantity.	bel under bo	e box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
		N/A	E10					nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
		398295	902-19-3/16	90:			2			175		Order Qty	Orde
	8	No(s)	component(s)	Con		LLC	devices, LLC			399744	39	Order No.	Orde
	lity	Heat Lot/Traceability	(-)				ontrol			902-19-3/16-10	902-19	Part No.	Par