Test Form 11/4/15	Te										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
	Ĕ.									o ivicetiii8			
										5 Meeting			
													8
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	ru	 Maintenance Tooling 			
			First Part Inspection Record	First Part I					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	3												
	2												
	1000												
	S S												
	>												
	110												
				i i									
													4
										7		S)	1/20
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Irs	put/8hrs					Time		Hrs.				
	٠	Thru-		Pcs./Hr			Cycle		Setup		r	Mach. No.	
							NAME OF TAXABLE PARTY OF TAXABLE PARTY.						
									Y.	Do not require traceability.	Do not requ	ā	Caps
							=	ot Number.	ved by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
							box label.	date on the	nber and	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
					1		etter "M."	g with the le	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
							ord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazin
							x quantity.	el under bo	e box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
	20293300	۵۱	A-RING					nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
	397478		AR15							3		Order Qty	Orde
	No(s)		component(s)	Col		LC	devices, LLC	7		397546	39	Order No.	Orde
	Heat Lot/Traceability	Heat	350505t(c)	2			o troi	ı		AR15-R	AR	Part No.	Par