Order Qty 21 W/O # from Box 3 9 / 3 2 9	CONTROL CONTRO
Order Qty 21 W/O # from Box 3 9 13 29 OPERATION 1 T	THRU-PUT/8HRS
OPERATION 1	THRU-PUT/8HRS
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Down time time Down time code Notes	Scrap Scrap Code
7 12/s/15 P.6. 41	1 11
Setup Hrs.	
Dmia.	
Cycle Time	,
2:25	7
Pcs/Hr Pcs/Hr	5
ROUTING:	
Down Down time	HRU-PUT/8HRS Scrap
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total time Notes	Scrap Code
Setup Hrs.	
Cycle Time	
Pcs/Hr	
ROUTING:	
	HRU-PUT/8HRS
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Down time time Down time code Notes	Scrap Scrap Code
Setup Hrs.	
Setup IIIs.	
Cycle Time	
Pcs/Hr	_
ROUTING:	
Notes / Instructions Down Time Codes First Part Inspection Record	
1 Maintenance Date Part Submitted Time Of Day Yes / No Check Letter Inspector	Notes
3 Setup 4 FAIR 12-3-15 9-15 1/25	
5 Training	2
6 Meeting	Tost Form 10/15/15