Dupluak

Test Form 11/4/15	Test F									RD	BRAZING PRODUCTION RECORD	BRAZING PR
									Training Meeting	6 5		
									FAIR	4 1		
		Notes	inspector	אבע רבוובו	Check	Yes / No	Tillie Of Day	Submitted	Tooling Setup	3 2		
				Dou lottor	Mtrl	Approved	Time of Day	Date Part	Maintenance	1		
			rt Inspection Record	First Part In					Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
			23						-			
	ľ											
		ŀ										
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					lime	s.	Hrs.			
		Thru-		Pcs./Hr			Cycle	dn	Setup		Mach. No.	
	L								Do not require traceability.	Do not requir	Caps/Plugs	Cap
							· =	/"Lot Number	Located on the bag followed by "Lot Number."	ocated on th	Snap Rings	Sna
			CP15				box label.	nd date on the	Use their work order number and date on the box label.	Use their wor	Flare Tubes	Flare
			CUTU-0-7/8	5	Property of the second		etter "M."	ting with the I	Located on the spool label, starting with the letter "M."	ocated on th	Copper Tubing	Coppe
			BRZ05				vord "heat."	tly above the v	Located on the box label, directly above the word "heat."	Located on th	Brazing Rings	Brazi
			BRZ09				ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. k	Flare Nuts	Flar
			CUTU-0-1/4	כנ				lumbers	Distinguishing Traceablity Numbers	Distinguis		
			7-4-9							3	Order Qty	Ord
		No(s)	Component(s)	Si Co		ררכ	devices, LLC	The state of the s	326	391326	Order No.	Orc
	ility	Heat Lot/Traceability		,			7)-24-C	S7-4-9-24-C	Part No.	Pa
						MAN						