Dort No.		3											
Order No.	39	394577		A	control devices LLC			Con	Component(s)	חבמו דטר	No(s)		
Order Qty		1			2				S	ع ا	394560	L	
	Distingu	Distinguishing Traceablity Numbers	ity Numb	ers					C-RING		N/A		
Flare Nuts	Six digit no.	Six digit no. located on the box label under box quantity.	box label	under bo	ox quantity.								
Brazing Rings	Located on	Located on the box label, directly above the word "heat."	directly ab	ove the v	vord "heat."								
Copper Tubing	Located on	Located on the spool label, starting with the letter "M."	, starting	with the l	etter "M."						0		
Flare Tubes	Use their w	Use their work order number and date on the box label.	er and da	ate on the	box label.								
Snap Rings	Located on	Located on the bag followed by "Lot Number."	ed by "Lot	Number	i i							1000	
Caps/Plugs	Do not requ	Do not require traceability.											
	Sandale season and season and			Name of the last o		ACM CONTRACTOR OF THE PERSON O	No.	Objective Separation and the separation of the s					STATE STATES
Mach. No.			Setup Hrs.		Cycle Time			Pcs./Hr		Thru- put/8hrs			
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Total	Down Time	Down Time Code			Notes		S	Scrap	Scrap Code
12/17 88		_											
,										/			
									A	25			
									5	1			
									17/1	5	-		
											-	X	
											+		
ROUTING:													
Special Notes / Instru	Instructions	Down Time (Codes					First Part Ir	rt Inspection Record				
- 1				Date Part)	Approved	Mtrl						
				Submitted	Time Of Day	Yes / No	Check	Rev Letter	Inspector		Notes		
		4 FAIR											
		5 Training											
BRAZING PRODUCTION REC	OBD	0										Tool Fo	
BRAZING PRODUCTION RECORD	CRU											Test Fo	Test Form 11/4/15