Test Form 11/4/15	Test									RD	BRAZING PRODUCTION RECORD	BRAZING PR
									Meeting	6 5		
									FAIR			
		Notes	Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted	Tooling Setup			
			Topoconor mecono		Mtr	Approved		Date Part	Maintenance	1		
			t Inspection Record	First Part I			The state of the s		Down Time Codes		Special Notes / Instructions	Specia
	(							100				ROUTING:
	7											
	?	J.										
		ナンジ										
		$^{\circ}$										
		-										
									0		98	3/4
Scrap Code	Scrap	٥	Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs. T	Emp. Name	Date
		put/siirs					lime					
		Thru-		Pcs./Hr			Cycle	, dp	Setup		Mach. No.	
						and the second second			i document.			000
									raceability	Do not require traceability		Cans
							=	"Lot Number.	Located on the bag followed by "Lot Number."	ocated on the		Snar
							e box label.	nd date on the	Use their work order number and date on the box label.	Jse their work	Flare Tubes	Flare
				50			etter "M."	ting with the I	Located on the spool label, starting with the letter "M."	ocated on the	Copper Tubing	Coppe
							vord "heat."	tly above the w	Located on the box label, directly above the word "heat."	ocated on the	Brazing Rings	Brazir
							эх quantity.	label under bo	Six digit no. located on the box label under box quantity.	ix digit no. loca	Flare Nuts S	Flan
		20140766	J-RING					lumbers	Distinguishing Traceablity Numbers	Distinguishi		
		998129	501-6-3/16	5(						10	Order Qty	Ord
		No(s)	component(s)	Col		LLC	devices, LLC	T.	w	399333	Order No.	Ord
	ility	Heat Lot/Traceability	anonont/cl				on troi	ı	.6-R	501-6-3/16-R	Part No.	Par
		. And										