Test Form 11/4/15	Test Fo								RD	BRAZING PRODUCTION RECORD	BRAZING PRO
								Training Meeting	6 5		
			\$ (#03)	SIL	1/13	10:15	3-7816	Setup FAIR	ε 4		
		Notes	Inspector	Mtrl Check Rev Letter	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2 1		
			rt Inspection Record	First Part				Down Time Codes	tions	Special Notes / Instructions	Special
	¢			×							ROUTING:
	P										
		9									
		2.1.5									
		7									
	9										
						B	6	6	30mia	20	3/28/16
Scrap Code	Scrap		Notes		Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs				lime	9	1113.	を できる ないがら		
		Thru-		Pcs./Hr		Cycle	" b	Setup		Mach. No.	
								Do not require traceability.	Do not requi	Caps/Plugs	Caps
						•=	"Lot Number.	Located on the bag followed by "Lot Number."	Located on th		Snap
			CP13			e box label.	nd date on the	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
			BRZ03			etter "M."	ting with the l	Located on the spool label, starting with the letter "M."	Located on th	Copper Tubing	Coppe
			CUTU-1-1/2		-	vord "heat.'	tly above the v	Located on the box label, directly above the word "heat."	Located on th	Brazing Rings	Brazir
			L-RING			ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. l	Flare Nuts	Flare
			11-1/2				lumbers	Distinguishing Traceablity Numbers	Distinguis		
			SF403-4-3/16					01	6	Order Qty	Orde
	-	No(s)	Component(s)		ררכ	devices, LLC	C)	405238	405	Order No.	Ord
	litv	Heat Lot/Traceability		3		 		3/16-1.5	S403-4-3/16-1.5	Part No.	Par