										כס	BRAZING BRODI ICTION BECOME	RAZING DR
									4 FAIR 5 Training 6 Meeting			
Notes		Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted	Ce		63 N .		
		rt Inspection Record	First Part In					e Codes			Special Notes / Instructions	Specia
												ROUTING:
	3											
	200	5										
	110											
									So	1	CC	2/5
		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
								lity.	Do not require traceability.	Do not requ	Caps/Plugs I	Caps
					1		ot Number.	wed by "L	Located on the bag followed by "Lot Number."	ocated on		Snap
						box label.	date on the	mber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	ng with the le	oel, startin	Located on the spool label, starting with the letter "M."	ocated on	Copper Tubing	Coppe
						ord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	_	Brazir
		ı	1			x quantity.	bel under bo	the box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
P	2	J-RING					nbers	ablity Nun	Distinguishing Traceablity Numbers	Distingu		
		J1/2							50		Order Qty	Ord
s)	No(s)	Component(s)	Con		TC	devices, LLC	1		400388	40	Order No.	Ord
race	Heat Lot/Traceability		)			S T T T T T T T T T T T T T T T T T T T			7T/7-V	1	raitivo.	Pa