									6 Meeting	0.11		
				Clieck	ies/ No							
	Notes	Inspector	Rev Letter	Mtrl	Approved	Time Of Day	Date Part Submitted		<ol> <li>Maintenance</li> <li>Tooling</li> </ol>			
		rt Inspection Record	First Part I					Codes	Down Time Codes	tions	Special Notes / Instructions	Speci
												ROUTING:
	~											
R												
	5											
	6,110.											
	5											
									250		SB	12/11
Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs		Pcs./Hr			Time		Hrs.			Mach. No.	
	Thru-					Cycle		Setup				
	2			L				Y.	Do not require traceability.	Do not requ	Caps/Plugs I	Сар
			i.e.	<b>I</b>		=	ot Number.	red by "L	Located on the bag followed by "Lot Number."	ocated on	Snap Rings	Sna
				I		box label.	date on the	ber and	Use their work order number and date on the box label	Jse their w	Flare Tubes	Flan
						etter "M."	g with the l	l, startin	Located on the spool label, starting with the letter "M."	ocated on	Copper Tubing	Coppe
						ord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	ocated on	Brazing Rings	Brazi
	20060667	E-RING		I		x quantity.	oel under bo	e box lak	Six digit no. located on the box label under box quantity.	six digit no.	Flare Nuts	Flar
_	N/A	E10					nbers	olity Nun	Distinguishing Traceablity Numbers	Distingu		
	389214	902-19-3/16	90	l				÷	250		Order Qty	Orc
	No(s)	component(s)	6		LLC	devices, LLC	£		392887	39	Order No.	Orc
	Heat Lot/Traceability	mnon+(c)	3			on troi	J		902-19-3/16-10	902-19	Part No.	Pa