

Service report - Haustech Baar GmbH (sample)

SAMPLE DOCUMENT - demo data, not a real receipt

Appliance: Vaillant ecoTEC plus VC 206/5-5

Work: burner and heat exchanger cleaned, ignition electrode checked

Flue gas: CO 18 ppm, NOx within limits (LRV)

System pressure set to 1.5 bar

Next service recommended in 12 months.