

# Industrial Brain AI RCA Report - P-101

## Incident Summary:

RCA draft: P-101 has 3 recorded failures. The dominant pattern is Seal Failure, supported by cited work o

## Likely Root Causes:

- shaft misalignment after seal replacement
- low suction pressure or blocked strainer causing cavitation

## Corrective and Preventive Actions:

- Verify alignment, coupling condition, and baseplate soft foot.
- Check suction pressure, strainer DP, and operating point against pump curve.
- Inspect seal flush plan and confirm correct spare part specification.
- Create follow-up work order and attach vibration trend evidence.

## Evidence:

- SOP\_22\_Pump\_Isolation.txt
- engineering\_notes\_P101.txt
- Factory\_Act\_Requirements.txt
- FlowServe\_P101\_Manual.txt
- inspection\_report\_P101.txt
- LOTO\_Procedure.txt
- maintenance\_work\_orders.csv
- near\_miss\_report.txt
- OISD\_Checklist.csv
- asset\_register.csv
- REG-PSM-Checklist.txt
- SOP-MECH-014\_pump\_isolation.txt
- WO-10421\_P-101\_mechanical\_seal.txt
- WO-10877\_P-101\_vibration\_repeat.txt
- Engineering\_Metadata\_Assets.csv