

Industrial Brain AI RCA Report - P-101

Incident Summary:

RCA draft: P-101 has 3 recorded failures. The dominant pattern is Seal Failure, supported by cited work o

Likely Root Causes:

- shaft misalignment after seal replacement
- low suction pressure or blocked strainer causing cavitation

Corrective and Preventive Actions:

- Verify alignment, coupling condition, and baseplate soft foot.
- Check suction pressure, strainer DP, and operating point against pump curve.
- Inspect seal flush plan and confirm correct spare part specification.
- Create follow-up work order and attach vibration trend evidence.

Evidence:

- asset_register.csv
- engineering_notes_P101.txt
- Factory_Act_Requirements.txt
- FlowServe_P101_Manual.txt
- inspection_report_P101.txt
- LOTO_Procedure.txt
- maintenance_work_orders.csv
- near_miss_report.txt
- OISD_Checklist.csv
- SOP_22_Pump_Isolation.txt
- Engineering_Metadata_Assets.csv
- REG-PSM-Checklist.txt
- SOP-MECH-014_pump_isolation.txt
- WO-10421_P-101_mechanical_seal.txt
- WO-10877_P-101_vibration_repeat.txt