Agilent Technologies

4263B LCR Meter Firmware Revision History

Note:
The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Agilent representative.

Revision 1.06 ... Released Feb. 2000

1. Change the brand HP to Agilent.

Revision 1.05 ... Released Feb. 1999

1. Fix the problem for Short correction value is large by only 100 kHZ on the test fixture.
2. Fix the problem for Load on/off marker indication of the LCD by GP-IB control.

Revision 1.04 ... Released Aug. 1998

1. Fix ADC Failure problem in save-recall function.

Revision 1.03 ... Released Jun. 1998

1. Fix ADC Failure problem.

Revision 1.02 ... Released Dec. 1997

1. Enhancement of 100kHZ measurement.

Revision 1.01 ... Released Jul. 1996

1. Fix ADC error problem.
2. Reduce the power on self test time.

Revision 1.00 ... Released Feb. 1996

1. Initial Release.