	P=1.0, Alpha=0.8				P=1.0, Alpha=0.9				P=1.0, Alpha=0.975			
30	-30.3	-31.4	-31.6	30	-30.4	-31.6	-31.7	30	-15.7	-16.7	-16.6	
p0=0.5 CP 90	-31.4	-31.9	-32.4	06	-31.4	-32.2	-32.3	06	-31.1	-32.3	-32.2	
150	-31.5	-32.3	-32.9	150	-31.8	-32.3	-32.8	150	-31.8	-32.7	-32.7	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-30.8	-31.5	-31.6	30	-30.6	-31.4	-31.4	30	-15.3	-16.0	-16.3	
p0=0.7 CP 90	-31.2	-32.4	-32.3	06	-31.4	-32.2	-32.4	06 -	-31.0	-31.8	-32.3	
150	-32.0	-32.6	-32.6	150	-31.8	-32.6	-32.7	150	-31.8	-32.7	-32.9	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-30.4	-31.3	-31.7	30	-30.0	-31.0	-31.7	30	-15.4	-16.3	-16.4	
p0=0.9 CP 90	-31.4	-31.9	-32.5	06	-31.5	-32.0	-32.4	06	-30.8	-28.6	-27.3	
150	-31.9	-32.3	-32.8	150	-31.7	-32.7	-32.8	150	-31.5	-32.2	-32.6	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-30.4	=5.0, Alpha=0 -31.0	-31.6	30	P=5.0, Alpha=0.9 -30.0 -31.0 -29.9				P=5.0, Alpha=0.975 -15.5 -15.6 -16.2			
p0=0.5 CP 90 3	-31.2	-32.0	-32.2	E 06	-31.2	-32.1	-32.2	06	-24.7	-30.8	-30.1	
p0.	-31.6	-32.2	-32.5	150	-31.4	-32.5	-32.4	150	-31.7	-32.2	-32.5	
1	1000	3000 Lk	5000	1	1000	3000 Lk	5000	1	1000	3000 Lk	5000	
30	-30.2	-31.6	-31.5	30	-28.5	-29.1	-29.5	30	-15.5	-16.0	-16.5	
p0=0.7 CP 90	-30.9	-32.0	-32.1	06	-31.3	-32.1	-32.7	06	-22.9	-18.0	-20.0	
p0 150	-31.6	-32.4	-32.7	150	-31.7	-32.4	-32.8	150	-31.0	-29.9	-32.5	
1	1000	3000 Lk	5000	-	1000	3000 Lk	5000	П	1000	3000 Lk	5000	
30	-30.6	-31.2	-32.0	30	-29.2	-24.7	-23.1	30	-15.4	-16.0	-16.1	
p0=0.9 CP 90	-31.2	-31.8	-32.5	06	-31.3	-32.1	-32.5	06	-15.7	-16.7	-18.2	
p0 150	-31.5	-31.8	-32.6	150	-31.9	-32.2	-32.8	150	-29.4	-29.0	-31.8	
15	1000	3000	5000	H ]	1000	3000	5000	11	1000	3000	5000	
	P=	Lk =10.0, Alpha=(	0.8		P=	Lk 10.0, Alpha=(	0.9		P=1	Lk 10.0, Alpha=0	.975	
30	-30.2	-31.2	-31.8	30	-29.2	-30.6	-29.7	30	-15.5	-15.6	-16.3	
p0=0.5 CP 90	-31.4	-32.0	-32.1	06	-31.0	-32.2	-32.2	06	-21.8	-20.4	-16.7	
150	-31.6	-32.1	-32.4	150	-31.5	-32.4	-32.4	150	-31.3	-31.9	-32.4	
	1000	3000 Lk	5000		1000	3000 Lk	5000	-	1000	3000 Lk	5000	
30	-30.5	-31.3	-31.9	30	-26.5	-23.1	-23.5	30	-15.6	-16.0	-16.3	
p0=0.7 CP 90	-31.2	-32.0	-32.5	06	-31.6	-31.7	-32.3	06	-17.4	-18.2	-18.4	
150	-31.5	-32.5	-32.6	150	-31.7	-32.1	-32.6	150	-27.8	-27.5	-32.1	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-30.7	-31.1	-31.5	30	-23.7	-23.3	-18.5	30	-15.4	-16.0	-16.1	
p0=0.9 CP 90	-31.2	-32.3	-32.4	06	-31.3	-32.0	-32.1	06 -	-15.7	-16.6	-16.6	
150	-31.4	-32.4	-32.5	150	-31.6	-32.4	-32.3	150	-27.7	-30.4	-24.2	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	