	P=1.0, Alpha=0.8				P=1.0, Alpha=0.9				P=1.0, Alpha=0.975			
30	-31.0	-32.0	-32.0	30	-31.0	-32.0	-32.0	30	-16.0	-19.0	-17.0	
p0=0.5 CP 90	-32.0	-33.0	-34.0	06	-32.0	-33.0	-33.0	06	-32.0	-33.0	-33.0	
150	-32.0	-33.0	-34.0	150	-33.0	-33.0	-33.0	150	-32.0	-33.0	-33.0	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-32.0	-33.0	-32.0	30	-32.0	-32.0	-32.0	30	-16.0	-17.0	-17.0	
p0=0.7 CP 90	-33.0	-34.0	-33.0	06	-32.0	-33.0	-33.0	06	-32.0	-33.0	-33.0	
150	-33.0	-34.0	-33.0	150	-33.0	-33.0	-33.0	150	-33.0	-33.0	-33.0	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-31.0	-32.0	-33.0	30	-31.0	-31.0	-33.0	30	-17.0	-18.0	-17.0	
p0=0.9 CP 90	-32.0	-33.0	-34.0	06	-32.0	-33.0	-33.0	06	-31.0	-32.0	-33.0	
150	-33.0	-33.0	-34.0	150	-32.0	-33.0	-33.0	150	-32.0	-33.0	-34.0	
	1000 P=	3000 Lk =5.0, Alpha=0.	000 5000 1000 Lk				3000 5000 Lk =5.0, Alpha=0.9			1000 3000 5000 Lk P=5.0, Alpha=0.975		
30	-31.0	-31.0	-32.0	30	-31.0	=5.0, Aipna=0 -32.0	-32.0	30	-18.0	-17.0	-17.0	
p0=0.5 CP 90	-32.0	-33.0	-33.0	06	-32.0	-33.0	-33.0	06	-31.0	-32.0	-33.0	
150	-32.0	-33.0	-33.0	150	-32.0	-33.0	-33.0	150	-33.0	-33.0	-33.0	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-31.0	-33.0	-32.0	30	-31.0	-31.0	-32.0	30	-16.0	-17.0	-19.0	
p0=0.7 CP 90	-31.0	-33.0	-33.0	06 -	-32.0	-33.0	-34.0	06	-30.0	-31.0	-31.0	
150	-32.0	-33.0	-33.0	150	-32.0	-33.0	-34.0	150	-32.0	-33.0	-33.0	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-32.0	-32.0	-33.0	30	-31.0	-32.0	-31.0	30	-17.0	-18.0	-17.0	
p0=0.9 CP 90	-32.0	-32.0	-33.0	06	-32.0	-33.0	-33.0	06	-17.0	-18.0	-31.0	
150	-32.0	-32.0	-33.0	150	-32.0	-33.0	-33.0	150	-31.0	-33.0	-33.0	
•	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-31.0	-32.0	-32.0	30	-30.0	=10.0, Alpha=(-32.0	-32.0	30	P=1 -18.0	.0.0, Alpha=0.	975 -17.0	
p0=0.5 CP 90	-32.0	-33.0	-33.0	06	-32.0	-33.0	-33.0	06	-32.0	-32.0	-18.0	
, 150	-32.0	-33.0	-33.0	150	-32.0	-33.0	-33.0	150	-32.0	-33.0	-34.0	
	1000	3000 Lk	5000	1	1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-32.0	-32.0	-32.0	30	-30.0	-32.0	-31.0	30	-16.0	-17.0	-17.0	
p0=0.7 CP 90	-32.0	-33.0	-33.0	06	-32.0	-32.0	-33.0	06	-30.0	-31.0	-31.0	
150	-32.0	-33.0	-33.0	150	-32.0	-33.0	-33.0	150	-32.0	-33.0	-33.0	
	1000	3000 Lk	5000		1000	3000 Lk	5000		1000	3000 Lk	5000	
30	-31.0	-32.0	-32.0	30	-31.0	-32.0	-30.0	30	-17.0	-18.0	-17.0	
p0=0.9 CP 90	-32.0	-33.0	-33.0	06	-32.0	-33.0	-33.0	06	-17.0	-18.0	-18.0	
150	-32.0	-34.0	-33.0	150	-32.0	-33.0	-33.0	150	-31.0	-33.0	-32.0	
	1000	3000 Lk	5000		1000	3000 Lk	5000	_	1000	3000 Lk	5000	