

INDUS HYUNDAI AUTHORIZED SERVICE CENTER
REPAIR ESTIMATE & QUOTATION

Estimate No: EST-88391

Customer: Rajesh Sharma

Vehicle No: KA01MJ4921

Date: 2026-08-22

Line Items:

1. Front Bumper Assembly - INR 18,500
 2. Headlight Unit Left - INR 14,000
 3. Painting & Labor Charges - INR 12,500
- Total Estimated Repair Cost: INR 45,000