

INDUS HYUNDAI AUTHORIZED SERVICE CENTER
REPAIR ESTIMATE & QUOTATION

Estimate No: EST-88395

Customer: Rajesh Sharma

Vehicle No: KA01MJ4921

Date: 2026-08-22

Line Items:

1. Rear Bumper Panel - INR 20,000

2. Tail Light Assembly - INR 12,000

Total Estimated Repair Cost: INR 32,000