Labour Charges are capped at ₹499 per appliance

Description	Service Charge
Non-Inverter PCB repaired	₹ 1,500
Inverter PCB repaired	₹ 4,000
Parlace IVT	₹ 900
Replace LVT	₹349 (Labour)
	₹ 350
Replace sensor	₹499 (Labour)
	₹ 500
Contactor replaced	₹499 (Labour)
	₹ 1,500
Contactor Daikin/ O-General	₹449 (Labour)
Convert PCB with remote	₹ 1,500
	₹ 250
Fan Capacitor - 2.5 to 10 mfd	₹349 (Labour)
Comp Capacitor - 25 to 60 mfd	₹ 400
	₹349 (Labour)
Combo Capacitor (Comp+Fan)	₹ 500
	₹349 (Labour)

Description	Service Charge
Gas Charging	₹ 2,500
Flair nut replaced	₹ 150
Cooling Coil / Condenser Coil repair	₹ 0
	₹500 (Labour)
Copper Coil Condensor 1 ton Split	₹ 3,500

Copper Coil Condensor 1.5 ton Split	₹ 4,000
Copper Coil Condensor 2 ton Split	₹ 4,500
Copper Cooling Coil (Split AC)	₹ 6,000
Capillary and filter replaced	₹ 350
Compressor 0.8-1 ton	₹ 6,500
Compressor 1.5 ton	₹ 7,500
Compressor 2 ton	₹ 9,200
Expansion valve replaced	₹ 1,200
Copper Cooling Coil/Condensor Coil (Window AC)	₹ 4,500
Replacement Compressor (1 Ton)	₹ 4,000
Replacement Compressor (1.5 Ton)	₹ 4,500
Replacement Compressor (2 Ton)	₹ 5,000
Service valve replaced - 1/4	₹ 400
Service valve replaced - 1/2	₹ 400

Service valve replaced - 5/8	₹ 500
Copper Cooling Coil (Split AC) - 1 Ton	₹ 5,000
Copper Cooling Coil (Split AC) - 1.5 Ton	₹ 6,000
Copper Cooling Coil (Split AC) - 2 Ton	₹ 7,000
Copper Cooling Coil (Split AC) O General & Mitshubishi - 1.5 Ton	₹ 7,000
Copper Cooling Coil/Condensor Coil (Window AC) - 1 Ton	₹ 4,000
Copper Cooling Coil/Condensor Coil (Window AC) - 1.5 Ton	₹ 4,500
Copper Cooling Coil/Condensor Coil (Window AC) - 2 Ton	₹ 5,000
Fuse Change in PCB	₹ 150 ₹299 (Labour)

Description	Service Charge
	₹ 1,800
Fan motor - Split AC	₹499 (Labour)
	₹ 2,200
Blower motor - Split AC	₹499 (Labour)
	₹ 1,100
Blower replaced	₹499 (Labour)
	₹ 400
Replace Flap/Swing Motor	₹499 (Labour)
Motor Bearing Change	₹ 1,000
	₹ 2,600
Fan motor - Window AC	₹499 (Labour)
	₹ 0
Noise issue repair	₹499 (Labour)

Description	Service Charge
1 meter copper pipe set (with insulation, wire)	₹ 900
Split AC Wall stand	₹ 750
Outdoor unit reinstalled	₹ 799
Indoor unit reinstalled	₹ 699
Fastner complete set	₹ 200
Floor stand	₹ 550
Universal back plate	₹ 300
AC Service Lite (window)	₹ 449
Lite AC service	₹ 519

Anti-rust deep clean AC service	₹ 949
Power saver AC service	₹ 619
Power Saver AC service (window)	₹ 549
AC installation	₹ 1,499
AC uninstallation	₹ 499
Anti-rust Spray (Avoid gas leak)	₹ 249

Description	Service Charge
Water Leakage Repaired- Split AC	₹ 100
	₹499 (Labour)
	₹ 0
Adjust Grill Locks	₹349 (Labour)
Adjust pipe and tight compressor screw	₹ 0
	₹349 (Labour)
	₹ 100
Connector wires replaced (1m)	₹349 (Labour)
	₹ 50
Tighten/ Replace Thimble	₹349 (Labour)
	₹ 0
External Dust/stick removal	₹399 (Labour)
	₹ 0
Insulation refix	₹399 (Labour)
	₹0
Drain pipe adjust	₹399 (Labour)
	₹0
Noise adjustment in motor	₹399 (Labour)
Noise adjustment in blower	₹ 0
	₹399 (Labour)
	₹ 0

Noise adjustment in cabinet	₹399 (Labour)
Noise adjustment in swing flap	₹0
	₹399 (Labour)
Water Leakage Repaired- Window AC	₹0
	₹449 (Labour)

Description	Service Charge
AC fan blade	₹ 700
	₹499 (Labour)
Grill Cover	₹ 1,500
	₹349 (Labour)
6 : 11 1 1	₹ 400
Swing blade replaced	₹349 (Labour)
Universal remote	₹ 800
	₹ 500
Water tray	₹200 (Labour)
Stabilizer repair	₹ 1,500
Sleeves (per piece)	₹ 50
Drain pipe adjust	₹ 100
Insulation refix	₹ 100
Noise issue repair	₹0
	₹499 (Labour)
Stabilizer connection	₹0
	₹399 (Labour)